



Aviat Networks LE3x00 Unlicensed Radio MD notification.

Dear Valued Customer,

It is our policy to continuously improve our product offering by looking ahead and providing new solutions for our customers' changing demands. The Aviat Networks LE3x00 Unlicensed radio platform sales have been declining and the time has come to reclassify its status. When it is determined that a product must be discontinued, Aviat Networks makes every commercially reasonable effort to:

- Provide 6 months notice so our customers can perform a needs assessment, obtain budget authorization, and place orders for radios and spares before the Last-Time-Buy end date
- Offer new products that are compatible with the products being discontinued to protect your radio network and Element/Network Management investment
- Make available Repair, Return, and Technical Support services during the 10 years after Last-Time-Buy announcement date. Services will provide, at best, 45 day turn around for units sent in for repair and may be procured through an Extended Warranty Support Agreement or Per Event Out of Warranty Repair requests.

This letter is to inform you that effective September 12, 2011 the Aviat Networks LE3x00 Unlicensed product line will enter a Last-Time-Buy period, which ends on March 12, 2012.

Effective March 12, 2012, the product will be reclassified as "Manufacturing Discontinued (MD)."

One of Aviat Networks' suggested replacement for the LE3x00 unlicensed radio is the IRU600 5.8/L6 GHz radio. This is a high power narrow band signal radio operating in the 5.8GHz unlicensed band (CFR47 Part 15.247 FCC and RSS-210 Annex 8 Industry Canada). It offers a unique low cost, low risk, low disruption ability to migrate later to the Lower 6 licensed band by simply changing the ACU (everything else remains the same).

If you require additional information, please contact your Aviat Networks Sales Representative.

Or you can visit one of the following:

Our Technical Assistance Center at 1-800-227-8332/1-210-561-7400/Fax 1-210-561-7399 or <http://www.support.aviatnetworks.com/>

Our Web Site: <http://www.aviatnetworks.com>

If this notification has been sent to you in error, please forward this letter to the person responsible for the operation and maintenance of your radio network immediately so they can take timely action.

Sincerely,

[Jennifer Beebe](#)

Product Manager